

State of Utah DEPARTMENT OF NATURAL RESOURCES DIVISION OF OIL, GAS AND MINING

355 West North Temple 3 Triad Center, Suite 350 Salt Lake City, Utah 84180-1203 801-538-5340

August 29, 1991

TO:

Minerals File

FROM:

Anthony A. Gallegos, Reclamation Engineer ad

RE:

Site Inspection, Native Asphalt, Cameron #1, S/047/036, Uintah County,

Utah

Inspection Date:

August 21, 1991

Inspection Time:

1800-1820

Conditions:

Overcast, windy

Participants:

Tony Gallegos, DOGM

The purpose of this inspection was to check on the current status of the operation.

The stockpile and scalped areas were essentially unchanged since the last DOGM inspection. The dike/dam across the wetlands area was breached with a small amount of water running through the breach. The stockpile and pit area show signs of some activity today with the front end loader located at the site. The pit has recently been worked, but there has been no increase in the amount of surface disturbance. Water from the wetland area was being diverted around the pit via a ditch and berm composed of asphalt material from the pit. The pit was not impounding water at this time. Photographs were taken to document the condition of the site.

jb

cc: Kathy Trott, Corp of Engineers

S047036.1



